



Don't use PB7 or PC10 for analog inputs

v_charge can be 4.2 volts
v_bckp must be 1.4 - 3.6 volts
I_bckp on the order of 15uA

mounting holes for 4-40 screws

SMA is optional default is wire whip

TeleMega